

# MEC LEAD CHARGE BAR PROGRESSIVE PRESS - MEC RELOADING 1-3/16OZ LEAD SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

The MEC Charge Bars allow you to adjust your shot charge and enable you to create the load you desire. Interchanges with the charge bar which is included with your reloading press. Available in both lead and steel styles for single stage and progressive presses. Steel shot bars are available by special order.



## Attributes

- Name: [MEC RELOADING 1-3/16OZ LEAD SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019418
- Mfr. No.: 5021316
- Size: 1-3/16 oz
- Delivery weight: 0.236kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489012836

## Item details

Made in USA

# Table of Contents

- [Startpage](#)
- [MEC Lead Charge Bar Progressive Press Safety Instructions](#)
- [About Us](#)

# MEC Lead Charge Bar Progressive Press Safety Instructions

## Introduction

Thank you for choosing the MEC Lead Charge Bar Progressive Press. This guide provides essential safety instructions to ensure safe use and handling of the product. Please read this document carefully before using the charge bar to ensure a safe and effective reloading experience.

## General Safety Guidelines

- Ensure that all users of the MEC Lead Charge Bar are familiar with the safety guidelines outlined in this document.
- Always use the charge bar in accordance with the manufacturer's instructions and recommendations.
- Keep the work area clean and organized to avoid accidents.
- Store the charge bar in a dry, secure location when not in use.
- Regularly inspect the charge bar for any signs of wear or damage. Do not use if damaged.
- Follow all local laws and regulations regarding the use of reloading equipment.

## Specific Safety Precautions for Use

- Use only the recommended shot types (lead or steel) with the charge bar.
- Ensure that the reloading press is securely mounted and stable before use.
- Wear appropriate personal protective equipment (PPE), including safety glasses and gloves, when handling shot and reloading components.
- Keep hands and clothing away from moving parts during operation.
- Do not exceed the recommended load limits when using the charge bar.
- Always doublecheck measurements before proceeding with reloading to avoid overloading or underloading.

## Instructions for Installation and Usage

### 1. Installation of the Charge Bar:

- Ensure the reloading press is turned off and unplugged.
- Remove the existing charge bar from the reloading press.
- Align the MEC Lead Charge Bar with the mounting points on the press.
- Secure the charge bar in place according to the manufacturer's instructions.
- Recheck that the charge bar is properly installed before use.

### 2. Using the Charge Bar:

- Adjust the charge bar to the desired shot charge by following the manufacturer's guidelines.
- Place the appropriate shot into the charge bar.
- Operate the reloading press according to the instructions provided with the press.
- Monitor the reloading process to ensure that the charge bar is functioning correctly.

### 3. PostUse Maintenance:

- Clean the charge bar after each use to remove any residue or debris.
- Inspect for any signs of wear or damage and replace if necessary.
- Store the charge bar in a safe location away from children and pets.

## **Disposal Instructions**

- Dispose of any damaged or wornout charge bars in accordance with local waste disposal regulations.
- Do not dispose of the charge bar in regular household waste if it contains hazardous materials.
- Check with local authorities for specific disposal guidelines for reloading equipment.

## **Contact Information for Further Support**

For any questions or concerns regarding the MEC Lead Charge Bar, please refer to the manufacturer's website or contact their customer service for assistance.

## **Conclusion**

By following the safety instructions outlined in this guide, you can ensure a safe and enjoyable reloading experience with the MEC Lead Charge Bar Progressive Press. Always prioritize safety and adhere to the guidelines provided to minimize risk and enhance your reloading activities.

# About Us

## Brownells UK

### **Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

Unit 1, Laughing Dog Industrial Estate  
London Road  
Rugby  
Warwickshire  
CV23 9LP

[www.brownells.co.uk](http://www.brownells.co.uk)