

MEC LEAD CHARGE BARS FOR SINGLE STAGE PRESS - MEC RELOADING 1-5/8OZ SINGLE STAGE LEAD SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

The MEC Charge Bars allow you to adjust your shot charge and enable you to create the load you desire. Interchanges with the charge bar which is included with your reloading press. Available in both lead and steel styles for single stage and progressive presses.



Attributes

- Name: [MEC RELOADING 1-5/8OZ SINGLE STAGE LEAD SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019408
- Mfr. No.: 302158
- Size: 1-5/8 oz
- Delivery weight: 0.238kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm

Item details

Made in USA

Table of Contents

- Startpage
- MEC Lead Charge Bars for Single Stage Press Safety Instruction Guide
- About Us

MEC Lead Charge Bars for Single Stage Press Safety Instruction Guide

Introduction

Thank you for choosing the MEC Lead Charge Bars for your single stage reloading press. These charge bars are designed to help you adjust your shot charge, enabling you to create the load you desire. This guide provides essential safety instructions to ensure safe and effective use of the product in compliance with the EU General Product Safety Regulation (GPSR).

General Safety Guidelines

- Ensure that you read and understand all instructions before using the MEC Lead Charge Bars.
- Always use the charge bars in accordance with the manufacturer's specifications and guidelines.
- Keep the product out of reach of children and vulnerable individuals to prevent accidents.
- Regularly inspect the charge bars for any signs of wear or damage before each use.
- Report any unsafe products or incidents to the relevant authorities immediately.
- Stay informed about product recalls by checking the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Always wear appropriate personal protective equipment (PPE), such as safety glasses and gloves, when handling lead shot and reloading materials.
- Ensure that your reloading press is securely mounted and stable before using the charge bars.
- Do not exceed the maximum charge weight specified for the charge bars (15/8 oz).
- Avoid inhaling dust or fumes that may be generated during the reloading process.
- Do not attempt to modify or alter the charge bars in any way.
- Store the charge bars in a cool, dry place away from direct sunlight and moisture.

Instructions for Installation and Usage

1. Installation:

- Ensure the reloading press is turned off and unplugged before installation.
- Remove the existing charge bar from the press if applicable.
- Align the MEC Lead Charge Bar with the mounting points on the reloading press.
- Securely attach the charge bar according to the manufacturer's instructions.

2. Usage:

- Adjust the charge bar to the desired shot charge weight (15/8 oz).
- Load the appropriate lead shot into the charge bar.
- Follow the reloading press's operating instructions to complete the reloading process.
- After use, clean the charge bar to remove any residue and store it safely.

Disposal Instructions

- Dispose of any used or damaged charge bars in accordance with local regulations regarding hazardous materials.
- Do not dispose of lead shot or other reloading materials in regular trash. Check with local waste management for proper disposal options.

Contact Information for Further Support

For safety inquiries or further assistance, please refer to the product packaging or visit the manufacturer's website for contact details.

Thank you for prioritizing safety while using the MEC Lead Charge Bars. Enjoy your reloading experience responsibly!

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk