

# MEC LEAD CHARGE BARS FOR SINGLE STAGE PRESS - MEC RELOADING 3/4OZ SINGLE STAGE LEAD SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

The MEC Charge Bars allow you to adjust your shot charge and enable you to create the load you desire. Interchanges with the charge bar which is included with your reloading press. Available in both lead and steel styles for single stage and progressive presses.



## Attributes

- Name: [MEC RELOADING 3/4OZ SINGLE STAGE LEAD SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019412
- Mfr. No.: 30234
- Size: 3/4 oz
- Delivery weight: 0.249kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489016933

## Item details

Made in USA

# Table of Contents

- [Startpage](#)
- [MEC Lead Charge Bars for Single Stage Press Safety Instruction Guide](#)
- [About Us](#)

# MEC Lead Charge Bars for Single Stage Press Safety Instruction Guide

## Introduction

Thank you for choosing the MEC Lead Charge Bars for your reloading needs. This guide provides important safety instructions and guidelines to ensure the safe and effective use of your MEC Lead Charge Bars. Please read this document carefully before using the product.

## General Safety Guidelines

- Ensure that all components of your reloading press are in good working condition before use.
- Always wear appropriate personal protective equipment (PPE), including safety glasses and gloves, when handling reloading components.
- Keep the reloading area clean and free of clutter to minimize risks of accidents.
- Store all reloading materials, including charge bars, in a secure location away from children and pets.
- Familiarize yourself with the specific safety instructions provided by the manufacturer of your reloading press.
- Report any unsafe products or accidents to the relevant authorities.

## Specific Safety Precautions for Use

- Do not exceed the maximum charge weight specified for your MEC Lead Charge Bar.
- Always doublecheck that the charge bar is securely attached to the reloading press before use.
- Avoid using the charge bar with incompatible materials or equipment.
- Ensure that the area is wellventilated when working with lead materials to minimize exposure to harmful fumes.
- If you experience any unusual behavior from the reloading press while in use, stop immediately and investigate the issue.

## Instructions for Installation and Usage

### 1. Installation of Charge Bar:

- Ensure your reloading press is turned off and unplugged.
- Remove the existing charge bar from the reloading press by following the manufacturer's instructions.
- Carefully align the MEC Lead Charge Bar with the mounting points of your press.
- Securely fasten the charge bar in place, ensuring there are no loose components.

### 2. Adjusting Shot Charge:

- Refer to the markings on the charge bar to select the desired shot charge weight.
- Make adjustments as needed, ensuring the settings correspond to your specific reloading requirements.

### 3. Loading Process:

- Prepare your reloading components, including hulls, primers, powder, and shot.
- Follow the reloading press manufacturer's instructions for loading procedures.
- Monitor the loading process closely to ensure consistent performance and safety.

### 4. PostUse Care:

- After use, clean the charge bar and surrounding area to prevent contamination and buildup of materials.
- Store the charge bar in a safe, dry place when not in use.

## **Disposal Instructions**

- Dispose of any lead materials, including spent charge bars, in accordance with local regulations regarding hazardous waste.
- Contact your local waste management authority for specific disposal guidelines related to lead and reloading materials.

## **Contact Information for Further Support**

For any questions or concerns regarding the MEC Lead Charge Bars or safety instructions, please refer to the manufacturer's official contact points or website for further assistance.

By following these safety instructions and guidelines, you can ensure a safe and effective reloading experience with your MEC Lead Charge Bars. Thank you for your attention to safety and responsible use.

# About Us

## Brownells UK

### **Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

Unit 1, Laughing Dog Industrial Estate  
London Road  
Rugby  
Warwickshire  
CV23 9LP

[www.brownells.co.uk](http://www.brownells.co.uk)