

MEC LEAD CHARGE BAR PROGRESSIVE PRESS - MEC RELOADING 1-5/8OZ LEAD SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

The MEC Charge Bars allow you to adjust your shot charge and enable you to create the load you desire. Interchanges with the charge bar which is included with your reloading press. Available in both lead and steel styles for single stage and progressive presses. Steel shot bars are available by special order.



Attributes

- Name: [MEC RELOADING 1-5/8OZ LEAD SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019421
- Mfr. No.: 502158
- Size: 1-5/8 oz
- Delivery weight: 0.231kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489014892

Item details

Made in USA

Table of Contents

- Startpage
- MEC Lead Charge Bar Progressive Press Safety Instructions
- About Us

MEC Lead Charge Bar Progressive Press Safety Instructions

Introduction

Thank you for choosing the MEC Lead Charge Bar Progressive Press. This product is designed to enhance your reloading experience by allowing you to adjust your shot charge according to your needs. To ensure safe and effective use of this product, please read and follow the safety instructions outlined in this guide.

General Safety Guidelines

- Always use the MEC Lead Charge Bar in accordance with the manufacturer's instructions.
- Keep the product away from children and vulnerable individuals.
- Inspect the charge bar regularly for any signs of wear or damage before use.
- Avoid using the charge bar with incompatible materials or equipment.
- Ensure that your reloading area is wellventilated and free from flammable materials.
- Do not overload your reloading press beyond the manufacturer's recommended limits.
- Report any unsafe conditions or accidents to the appropriate authorities.

Specific Safety Precautions for Use

- Wear appropriate personal protective equipment (PPE), such as safety glasses and gloves, when using the charge bar.
- Ensure that your workspace is clean and organized to prevent accidents.
- Do not use the charge bar if you are tired or under the influence of drugs or alcohol.
- Always follow the recommended procedures for loading and unloading materials to prevent spills and accidents.
- Be aware of the potential hazards associated with lead and steel shot materials, including lead exposure.

Instructions for Installation and Usage

Installation

1. **Preparation:** Ensure the reloading press is turned off and unplugged.
2. **Remove Existing Charge Bar:** If applicable, carefully remove the existing charge bar from the reloading press.
3. **Install the MEC Charge Bar:**
 - Align the MEC Lead Charge Bar with the mounting points on your reloading press.
 - Secure the charge bar in place according to the manufacturer's instructions.
4. **Check for Proper Installation:** Ensure that the charge bar is firmly attached and does not move when pushed.

Usage

- **Adjusting Shot Charge:**
 - Follow the manufacturer's guidelines for adjusting the shot charge to your desired weight.
 - Make sure to securely lock any adjustment settings before use.
- **Reloading Process:**
 - Begin the reloading process by following the stepbystep instructions specific to your reloading press.
 - Always monitor the operation closely to ensure safe functionality.
- **PostUse Maintenance:**
 - After use, clean the charge bar and surrounding area to prevent residue buildup.
 - Store the charge bar in a safe, dry place when not in use.

Disposal Instructions

- Dispose of any materials used with the MEC Lead Charge Bar, including lead and steel shot, in accordance with local regulations.
- Do not dispose of the charge bar in regular household waste. Follow local guidelines for disposing of metal and reloading components.

Contact Information for Further Support

For any inquiries regarding the MEC Lead Charge Bar or safety concerns, please refer to the manufacturer's contact information provided on the product packaging or website.

By adhering to these safety instructions, you can ensure a safe and efficient reloading experience with your MEC Lead Charge Bar Progressive Press. Thank you for prioritizing safety while enjoying your reloading activities.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk