

MEC LEAD CHARGE BAR PROGRESSIVE PRESS - MEC RELOADING 3/4OZ LEAD SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

The MEC Charge Bars allow you to adjust your shot charge and enable you to create the load you desire. Interchanges with the charge bar which is included with your reloading press. Available in both lead and steel styles for single stage and progressive presses. Steel shot bars are available by special order.



Attributes

- Name: [MEC RELOADING 3/4OZ LEAD SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019423
- Mfr. No.: 50234
- Size: 3/4 oz
- Delivery weight: 0.243kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489016148

Item details

Made in USA

Table of Contents

- Startpage
- MEC Lead Charge Bar Progressive Press Safety Instruction Guide
- About Us

MEC Lead Charge Bar Progressive Press Safety Instruction Guide

Introduction

Thank you for choosing the MEC Lead Charge Bar Progressive Press. This product is designed to help you adjust your shot charge and create the load you desire for reloading. Please read this safety instruction guide carefully to ensure safe and effective use of the product.

General Safety Guidelines

- Always ensure that the MEC Lead Charge Bar is used in accordance with the manufacturer's instructions.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the Charge Bar for any signs of wear or damage before use.
- Do not use the Charge Bar for any purpose other than intended.
- In case of an emergency or unsafe situation, discontinue use immediately and seek assistance.

Specific Safety Precautions for Use

- **Hazard Identification:**
 - Improper use may lead to injury or accidents.
 - Ensure that all components are securely attached before operating the press.
- **Avoiding Hazards:**
 - Always wear appropriate safety gear, including safety glasses and gloves, when using the Charge Bar.
 - Do not exceed the recommended shot charge limits for the Charge Bar.
 - Ensure your workspace is clean, dry, and welllit to prevent accidents.
- **Audience Specific Warnings:**
 - This product is not recommended for use by individuals under the age of 18 without adult supervision.

Instructions for Installation and Usage

1. Installation:

- Ensure that the reloading press is turned off and disconnected from any power source before installation.
- Remove the existing charge bar from the reloading press by following the manufacturer's instructions.
- Carefully attach the MEC Lead Charge Bar to the reloading press, ensuring it is securely fastened.
- Doublecheck all connections to ensure safety during operation.

2. Usage:

- Adjust the shot charge as desired by following the instructions provided with the Charge Bar.
- Always check the Charge Bar settings before starting the reloading process.
- Monitor the reloading process closely to ensure everything operates smoothly.
- If any issues arise during use, stop immediately and assess the situation before proceeding.

Disposal Instructions

- Dispose of the MEC Lead Charge Bar according to local regulations.
- Ensure that all components are disposed of in an environmentally friendly manner.

- Do not throw the Charge Bar in regular waste; check for recycling options in your area.

Contact Information for Further Support

For safety inquiries or further assistance, please refer to the manufacturer's contact information provided with your product.

Conclusion

By following these safety instructions, you can ensure that your experience with the MEC Lead Charge Bar Progressive Press is safe and efficient. Always prioritize safety and do not hesitate to seek assistance if needed. Thank you for your attention and happy reloading!

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk