

GAS CHECKS - 30 CALIBER GAS CHECKS 1,000/BOX

[Reloading](#) > [Bullet Casting](#) > [Gas Checks](#)

If you cast your own bullets, Hornady's crimp-on gas checks will enhance their performance. During sizing, the gas check crimps to the base of cast lead bullets to seal gasses and protect the base from deformation. Hornady gas checks are the only real choice for bullet casters. Packaged 1000 per box.



Attributes

- Name: [30 CALIBER GAS CHECKS 1,000/BOX](#)
- Manufacturer: [HORNADY](#)
- Product no.: 749012045
- Mfr. No.: 7070
- Quantity: 1,000
- Delivery weight: 0.318kg
- Shipping height: 51mm
- Shipping width: 69mm
- Shipping length: 107mm
- UPC: 090255270709

Item details

Made in USA

US export classification: 0A505.x

Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for Hornady 30 Caliber Gas Checks](#)
- [About Us](#)

Safety Instruction Guide for Hornady 30 Caliber Gas Checks

Introduction

Thank you for choosing Hornady 30 Caliber Gas Checks. These crimp gas checks are designed to enhance the performance of cast lead bullets by sealing gases and protecting the base from deformation. This guide provides important safety information and instructions for the safe use of this product in compliance with the EU General Product Safety Regulation (GPSR).

General Safety Guidelines

- Ensure that the product is used only for its intended purpose.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly check for any updates or safety recalls on the EU Safety Gate platform.
- Report any unsafe products or accidents to the relevant authorities.

Specific Safety Precautions for Use

- Always wear appropriate safety gear, including safety glasses and gloves, when handling lead or related materials.
- Ensure proper ventilation in your workspace to avoid inhalation of fumes generated during bullet casting.
- Be aware of the risks associated with melting lead, including burns and exposure to toxic fumes.
- Do not consume food or drink in the area where lead casting or handling occurs.
- Store gas checks in a cool, dry place away from direct sunlight and moisture.

Instructions for Installation and Usage

1. Preparation:

- Gather all necessary tools and materials, including a sizing die and bullet casting equipment.
- Ensure your workspace is clean and organized.

2. Installation of Gas Checks:

- Select a gas check that matches the caliber of your cast bullets (30 caliber in this case).
- Place the gas check onto the base of the cast bullet.
- Use a sizing die to crimp the gas check onto the bullet base securely.

3. Usage:

- Once installed, the gas check will help seal gases during firing, enhancing bullet performance.
- Regularly inspect the gas checks during use to ensure they remain properly secured.

4. PostUse:

- Clean your tools and workspace after use to avoid contamination from lead residues.
- Dispose of any unused or damaged gas checks according to local regulations.

Disposal Instructions

- Dispose of any unused or damaged gas checks in accordance with local waste management regulations.
- If lead contamination occurs, follow proper procedures for lead disposal to prevent environmental harm.

Contact Information for Further Support

For any safety inquiries or additional information regarding the use of Hornady 30 Caliber Gas Checks, please refer to the manufacturer's website or contact your local distributor.

Thank you for your attention to these safety guidelines. Your safety is our priority.

About Us

Brownells Česká republika

Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

www.brownells.cz