

GAS CHECKS - 35 CALIBER GAS CHECKS 1,000/BOX

[Reloading](#) > [Bullet Casting](#) > [Gas Checks](#)

If you cast your own bullets, Hornady's crimp-on gas checks will enhance their performance. During sizing, the gas check crimps to the base of cast lead bullets to seal gasses and protect the base from deformation. Hornady gas checks are the only real choice for bullet casters. Packaged 1000 per box.



Attributes

- Name: [35 CALIBER GAS CHECKS 1,000/BOX](#)
- Manufacturer: [HORNADY](#)
- Product no.: 749012048
- Mfr. No.: 7110
- Quantity: 1,000
- Delivery weight: 0.249kg
- Shipping height: 56mm
- Shipping width: 66mm
- Shipping length: 104mm
- UPC: 090255271102

Item details

Made in USA

US export classification: 0A505.x

Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for Hornady Gas Checks 35 Caliber](#)
- [About Us](#)

Safety Instruction Guide for Hornady Gas Checks 35 Caliber

Introduction

Thank you for choosing Hornady Gas Checks 35 Caliber. This guide provides important safety information and instructions for the safe use of this product. Please read this guide carefully to ensure safe handling and usage.

General Safety Guidelines

- Always use Hornady Gas Checks in accordance with the manufacturer's guidelines.
- Ensure that the product is stored in a cool, dry place away from direct sunlight.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly check for any signs of damage or wear before use.
- Report any unsafe products or accidents to the relevant authorities.
- Stay updated on recall notices through the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Use appropriate personal protective equipment (PPE), such as safety glasses and gloves, when handling gas checks.
- Avoid inhalation of any dust that may be generated during the use of gas checks.
- Ensure proper ventilation in the area where you are casting bullets.
- Do not use gas checks with incompatible materials or processes.
- Always follow the recommended sizing procedures to prevent deformation or other hazards.

Instructions for Installation and Usage

1. Preparation:

- Gather all necessary materials, including your cast lead bullets and Hornady Gas Checks.
- Ensure your workspace is clean and organized.

2. Installation of Gas Checks:

- Place the gas check on the base of the cast lead bullet.
- Use a sizing die to crimp the gas check onto the bullet. Ensure that the gas check is securely attached.
- Inspect the bullets to confirm that the gas checks are properly installed without deformation.

3. Usage:

- Use the bullets with gas checks in accordance with your reloading data and firearm specifications.
- Monitor the performance of your ammunition and inspect for any irregularities after firing.

Disposal Instructions

- Dispose of any unused or damaged gas checks in accordance with local regulations.
- Do not dispose of gas checks in household waste. Instead, check for local recycling options or hazardous waste disposal facilities.

Contact Information for Further Support

For any inquiries regarding safety, usage, or recalls, please refer to the manufacturer's contact information provided on the packaging or visit the official website.

By following these safety instructions, you can ensure a safe and effective experience with Hornady Gas Checks 35 Caliber. Thank you for your attention to safety!

About Us

Brownells Česká republika

Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

www.brownells.cz