

GAS CHECKS - 416 CALIBER GAS CHECKS 1,000/BOX

[Reloading](#) > [Bullet Casting](#) > [Gas Checks](#)

If you cast your own bullets, Hornady's crimp-on gas checks will enhance their performance. During sizing, the gas check crimps to the base of cast lead bullets to seal gasses and protect the base from deformation. Hornady gas checks are the only real choice for bullet casters. Packaged 1000 per box.



Attributes

- Name: [416 CALIBER GAS CHECKS 1,000/BOX](#)
- Manufacturer: [HORNADY](#)
- Product no.: 749012050
- Mfr. No.: 7125
- Quantity: 1,000
- Delivery weight: 0.476kg
- Shipping height: 56mm
- Shipping width: 89mm
- Shipping length: 107mm
- UPC: 090255271256

Item details

Made in USA

EU Export Disabled

US export classification: 0A505.x

Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for Hornady 416 Caliber Gas Checks](#)
- [About Us](#)

Safety Instruction Guide for Hornady 416 Caliber Gas Checks

Introduction

Thank you for choosing Hornady 416 Caliber Gas Checks. These crimp gas checks are designed to enhance the performance of your cast lead bullets. This guide provides essential safety instructions to ensure the safe use of this product, in compliance with the EU General Product Safety Regulation (GPSR).

General Safety Guidelines

- Always use Hornady gas checks in accordance with the manufacturer's recommendations.
- Ensure that the product is stored in a safe, dry place, away from direct sunlight and moisture.
- Keep gas checks out of reach of children and vulnerable individuals.
- Regularly check for any product recalls or safety alerts through the EU's Safety Gate platform.
- Report any unsafe product incidents or accidents to the appropriate authorities.

Specific Safety Precautions for Use

- Handle gas checks with care to avoid injury. Sharp edges may be present.
- Always wear appropriate personal protective equipment (PPE) such as gloves and safety glasses when handling.
- Ensure proper ventilation when using gas checks in conjunction with casting equipment.
- Do not use gas checks with incompatible bullet types or materials.
- Inspect gas checks before use. Do not use if damaged or deformed.

Instructions for Installation and Usage

1. Preparation:

- Gather all necessary tools and materials, including your casting equipment and Hornady gas checks.
- Ensure your work area is clean and organized.

2. Installation of Gas Checks:

- Place the gas check on the base of the cast lead bullet.
- Use a crimping tool or sizing die to securely crimp the gas check onto the bullet base.
- Ensure that the gas check is properly seated and sealed to prevent gas leakage during firing.

3. Usage:

- Load the bullets into your firearm according to the manufacturer's instructions.
- Follow all safety protocols for handling and firing your firearm.
- After firing, inspect the bullets and gas checks for any signs of deformation or damage.

Disposal Instructions

- Dispose of any unused or defective gas checks in accordance with local regulations.
- Do not dispose of gas checks in regular household waste. Check for designated disposal sites or recycling programs.
- Ensure that all packaging materials are disposed of responsibly.

Contact Information for Further Support

For any safety inquiries related to Hornady gas checks, please refer to the manufacturer's website or contact their customer support. It is important to have access to expert advice for any concerns regarding product safety and usage.

By following these safety instructions, you can ensure a safer experience while using Hornady 416 Caliber Gas Checks. Always prioritize safety and stay informed about best practices for product use.

About Us

Brownells Deutschland

**Brownells Deutschland - Einer der größten Lieferanten für Waffenteile,
Büchsenmacherwerkzeug & Schießsportzubehör**

Lahnstraße 1
24539 Neumünster
Deutschland

www.brownells-deutschland.de