

MEC LEAD CHARGE BARS FOR SINGLE STAGE PRESS - MEC RELOADING 1-1/2OZ SINGLE STAGE LEAD SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

The MEC Charge Bars allow you to adjust your shot charge and enable you to create the load you desire. Interchanges with the charge bar which is included with your reloading press. Available in both lead and steel styles for single stage and progressive presses.



Attributes

- Name: [MEC RELOADING 1-1/2OZ SINGLE STAGE LEAD SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019403
- Mfr. No.: 302112
- Size: 1-1/2 oz
- Delivery weight: 0.238kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489011051

Item details

Made in USA

Table of Contents

- Startpage
- MEC Lead Charge Bars Safety Instruction Guide
- About Us

MEC Lead Charge Bars Safety Instruction Guide

Introduction

Thank you for choosing the MEC Lead Charge Bars for your reloading needs. These charge bars are designed to help you adjust your shot charge for optimal performance in singlestage and progressive presses. This guide provides essential safety instructions to ensure safe usage and compliance with the EU General Product Safety Regulation (GPSR).

General Safety Guidelines

- Always read and follow the manufacturer's instructions before using the product.
- Ensure that the product is used in accordance with its intended purpose.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage before use.
- Report any unsafe products or accidents to the appropriate authorities.
- Stay informed about product recalls by checking the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Use only in conjunction with compatible MEC reloading presses.
- Ensure that the charge bar is securely attached before operating the press.
- Avoid overloading the charge bar beyond its specified capacity (11/2 oz).
- Wear appropriate safety gear, including safety glasses and gloves, when handling materials.
- Do not attempt to modify the charge bar or use it for any purpose other than intended.

Instructions for Installation and Usage

1. Installation:

- Unpack the MEC Lead Charge Bar and ensure all components are included.
- Refer to your reloading press manual for specific installation instructions.
- Align the charge bar with the designated slot on your reloading press.
- Securely fasten the charge bar according to the manufacturer's specifications.

2. Usage:

- Set your desired shot charge by adjusting the charge bar.
- Load the appropriate materials into the press as per the reloading guidelines.
- Operate the press according to the instructions provided in your reloading press manual.
- After use, clean the charge bar and surrounding area to prevent any residue buildup.

Disposal Instructions

- Dispose of the MEC Lead Charge Bar in accordance with local waste disposal regulations.
- Do not dispose of the product in household waste; check for recycling options.
- If the product is damaged or no longer usable, contact your local waste management authority for proper disposal methods.

Contact Information for Further Support

For further assistance regarding the MEC Lead Charge Bars, please refer to the manufacturer's contact information provided with your product packaging. It is important to reach out for any safety inquiries or

concerns.

Thank you for prioritizing safety while using the MEC Lead Charge Bars. Your compliance with these guidelines ensures a safer reloading experience.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk