

MEC POWDER BUSHINGS - MEC RELOADING #40 POWDER BUSHING

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

We stock a variety of the MEC powder bushings. Each bushing holds a unique volume enabling you to adjust the powder load for your rounds. It is always recommended to use a scale to check powder weights for accuracy. We offer individual bushings in #7 thru #13 and #16 thru #38. Please refer to the MEC website for powder charts that will give you a recommended bushing and start point for your specific powder at www.mecreloaders.com



Attributes

- Name: [MEC RELOADING #40 POWDER BUSHING](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019459
- Mfr. No.: 5040
- Size: -
- Delivery weight: 0.007kg
- Shipping height: 19mm
- Shipping width: 114mm
- Shipping length: 186mm
- UPC: 098489016025

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [MEC Powder Bushings Safety Instruction Guide](#)
- [About Us](#)

MEC Powder Bushings Safety Instruction Guide

Introduction

Thank you for choosing the MEC Powder Bushings for your reloading needs. This guide provides essential safety instructions and best practices to ensure the safe and effective use of our product. Please read this document carefully before using the MEC Powder Bushings.

General Safety Guidelines

- Always use the MEC Powder Bushings in accordance with the manufacturer's instructions.
- Ensure that the workspace is clean, organized, and free from distractions while reloading.
- Keep the powder bushings out of reach of children and pets.
- Use protective eyewear and gloves when handling powders and reloading equipment.
- Be aware of the properties and hazards of the powders you are using. Refer to the powder's safety data sheet (SDS) for specific information.
- Regularly inspect the powder bushings for wear or damage before each use.
- Store powder bushings in a cool, dry place away from direct sunlight and moisture.

Specific Safety Precautions for Use

- Ensure that the correct bushing size is selected for your specific powder and load requirements.
- Use a scale to check powder weights for accuracy before loading cartridges.
- Do not exceed the recommended maximum powder load for your specific bushing.
- Avoid mixing different types of powders in the same container.
- Always follow the recommended procedures for cleaning and maintaining your reloading equipment.
- If you notice any irregularities during the reloading process, stop immediately and investigate the issue before proceeding.

Instructions for Installation and Usage

1. Selecting the Bushing:

- Choose the appropriate MEC Powder Bushing based on the desired powder load and the specifications provided on the MEC website.

2. Installation:

- Remove the existing bushing from your reloading press, if applicable.
- Carefully insert the selected MEC Powder Bushing into the designated bushing holder of your reloading press.
- Ensure that the bushing is securely in place and properly seated.

3. Adjusting Powder Load:

- Use the scale to measure the desired powder charge.
- Adjust the bushing as necessary to achieve the correct powder load.
- Doublecheck the weight before proceeding to load cartridges.

4. Loading Cartridges:

- Follow your reloading manual's instructions for the specific cartridge you are loading.
- Monitor the powder dispensing process to ensure consistent charges.

5. PostUsage Care:

- After reloading, clean the bushing and surrounding area to prevent powder residue buildup.
- Store the powder bushings in their designated containers to avoid damage.

Disposal Instructions

- Dispose of any unused powder in accordance with local regulations.
- Do not dispose of powder bushings in regular household waste. Check local guidelines for proper disposal methods for reloading components.
- Ensure that all materials are disposed of safely to prevent environmental contamination.

Contact Information for Further Support

For additional support or inquiries regarding the MEC Powder Bushings, please refer to the MEC website or contact your local MEC dealer. Always keep this manual for future reference and ensure that all users have access to the safety instructions outlined herein.

By following these safety guidelines and instructions, you will help ensure a safe and efficient reloading experience. Thank you for choosing MEC Powder Bushings, and happy reloading!

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk